



June 2, 1999

Division of Oil, Gas and Mining 1594 West North Temple, Suite 1210 P.O. Box 145801 Salt Lake City, Utah 84114-5801

Attention: Jim Smith

ACT/015/018 #7 ACT/015/017 #7 ACT/015/019 #7 COPY JOE

Re: Revised Volume 9 Hydrologic Section, PacifiCorp, Des-Bee-Dove mines, ACT/015/017, Deer Creek Mine, ACT/015/018, Cottonwood Mine, ACT/015/019

PacifiCorp, by and through its wholly-owned subsidiary, Energy West Mining Company ("Energy West") as mine operator, hereby submits a revised Volume 9 Hydrologic Section for the following mines: Cottonwood Mine Act/015/019, Deer Creek Mine Act/015/018 and Des-Bee-Dove mines Act/015/017 in response to concerns raised during our meeting on May 26, 1999.

The concerns raised during the review include:

Concern:

R645-301-712,-731.700. HM-5 is certified by an AIPG certified professional

geologist: AIPG certification does not meet the requirements of the Utah Coal

Mining Rules...

Response:

Map HM-5 has been certified by a professional engineer.

Concern:

R645-301-724.300. It is stated on page 81 that the relationship of Little Bear Spring to Mill Fork graben is shown on HM-6: the location of Little Bear Spring

is on HM-6, which is a reproduction of a USGS map, but HM-6 does not show the faults or graben. HM-7 shows the relationship of the spring to the graben.

Response:

Page 81 has been revised to state: "As illustrated on HM-7, Little Bear

Spring is directly in line with the western edge of the graben....".

Concern:

R645-301-121.200, 724. Even-numbered pages in the copy of the report by

Echosystem Research Institute in Hydrologic Support Information 3 were copied

off-center and text and numbers.

DOGM Volume 9 Revisions Page Two June 2, 1999

Response:

Reproduction error, enclosed is 10 copies to be inserted in Hydrologic

Support Information #3.

Concern:

R645-301-121,200, -724.300. The PHC refers to section R645-301-722 for data

used to arrive at the conclusions of the PHC (p. 128).

Response:

Text on page 128 has been revised to correctly state "Data utilized to arrive at

the conclusions presented in this section were discussed earlier (see Section

R645-301-721).....

Enclosed is seven copies of the following information for your review:

Revisions to Volume 9 - Hydrologic Section:

Volume 9 HYDROLOGY

Replace Map HM-5 (certification did not meet the requirements of the Utah Coal Mining Rules).

Replace text section pages 81-82 and 127-128 (revised to address the concerns listed above).

Replace Hydrologic Support Information #3 (Reproduction error).

If you have any questions or concerns regarding this submittal, please feel free to contact myself at 687-4720 or Dennis Oakley at 687-4825.

Sincerely,

Charles A. Semborski

Geology/Permitting Supervisor

CAS/cas

cc:

Blake Webster (InterWest Mining Company)

Carl Pollastro (Energy West Mining Company)

Dennis Oakley (Energy West Mining Company)

I:\PCCOMMON\PCCOMMON\ENVIRONM\PERMITS\EMHYDRO\VOL9REV 699